

Hartlepool Borough Council

Environmental Inspection Report – 1st Quarter

MARAD Contract

November 2008



Prepared for:



Revision Schedule

MARAD Contract Environmental Inspection Report - 1st Quarter November 2008

D115634

Rev	Date	Details	Prepared by	Reviewed by	Approved by
01	November 2008	Final	Adrian Milton Principal Environmental Specialist	Matthew Smedley Principal Pranner	Neil Stephenson Technical Director

This document has been prepared in accordance with the scope of Scott Wilson's appointment with its client and is subject to the terms of that appointment. It is addressed to and for the sole and confidential use and reliance of Scott Wilson's client. Scott Wilson accepts no liability for any use of this document other than by its client and only for the purposes for which it was prepared and provided. No person other than the client may copy (in whole or in part) use or rely on the contents of this document, without the prior written permission of the Company Secretary of Scott Wilson Ltd. Any advice, opinions, or recommendations within this document should be read and relied upon only in the context of the document as a whole. The contents of this document do not provide legal or tax advice or opinion.

Scott Wilson WESTONE Wellington Street Leeds West Yorkshire LS1 1BA

Tel 0113 2045000 Fax 0113 2045001

Table of Contents

1	Introduction	1
2	Inspection Methodology	2
3	Observations and Corrective Actions	4
4	Conclusions and Recommendations	5

Appendix

1. Completed Visit Proformas

1 Introduction

- 1.1 Scott Wilson has been appointed by Hartlepool Borough Council to provide planning and environmental advice with respect to the TERRC (Teesside Environmental Reclamation & Recycling Centre) development and operation.
- 1.2 Under the Section 106 agreement for the development the site operator (Able UK) is required to establish the TERRC Ecological Advisory Group (TEAG) to provide information and advice with respect to ecological issues relating to the project.
- 1.3 Furthermore, paragraph 5.5, of Schedule 2 of s106 agreement states that:

"During the period of dismantling the ships comprised in the MARAD contract the Council may appoint an environmental inspector (or inspectors to a single person full time equivalent) for the purpose of monitoring the ship dismantling. The Developer shall pay the reasonable employment costs of the environmental inspector, afford him daily access to the Site in accordance with arrangements agreed in consultation between the Council and the Developer and supply all such information as he shall reasonably request (including the opportunity to meet with the Environmental Manager), PROVIDED ALWAYS that before being supplied with information that is commercially confidential the auditor shall first have signed an appropriate confidentiality agreement in respect of such confidential information and whilst at TERRC shall comply with the health and safety requirements of the Developer;"

- 1.4 Hartlepool Borough Council has appointed Scott Wilson to fulfil the role of Environmental Inspector for the purpose of monitoring the dismantling of the MARAD ships. The environmental Inspector is independent of Able UK and Hartlepool Borough Council. This is independent role which supplements the formal regulator inspections of, for example the Environment Agency and the Health and Safety Executive. Furthermore, Able UK's asbestos removal activities are monitored by an independent specialist contractor (Franks Portlock Consulting Limited).
- 1.5 This report is the first quarterly inspection report and provides details of the inspection methodology, observations from inspections completed to date and recommendations for future inspections. It highlights any environmental issues identified or addressed during the course of the first quarter, and any remedial actions or agreements made with to these issues by either Able UK or Hartlepool Borough Council.

2 Inspection Methodology

- 2.1 With the agreement of Hartlepool Borough Council and Able UK the nominated Environmental Inspector has carried-out a number of site visits commensurate with the levels of environmental risks associated with the ongoing works. These visits have included both pre-announced and unannounced visits.
- 2.2 Each visit followed the general programme set-out below:
 - general update from MARAD project manager on the progress and status of ship dismantling;
 - review of environmental monitoring reports/data completed by Able UK and their contractors since the last inspection;
 - visual inspection of areas around MARAD ships; and
 - visual inspection of asbestos removal activities on-ship.
- During each visit a site inspection proforma was completed and the findings agreed and signed by both the inspector and the MARAD project manager. Completed proformas are attached as Appendix A. It should be noted that amendments to the proforma have been made during the inspection period to ensure it is appropriate for purpose.
- Due to confidentiality agreement with the MADAD ship owners no photographic record is generally collected. However, if photographs were required then they could be taken by an Able UK representative and special dispensation sought for their release. This is the only restriction on the inspections, with free and open access available to all areas of the MARAD dismantling operations.
- 2.5 At the time of reporting a total of seven inspection visits have been completed. These were undertaken on:
 - Friday 05 Sept 08;
 - Tuesday 09 Sept 08;
 - Wednesday 01 Oct 08;
 - Friday 17 Oct 08;
 - Thursday 06 Nov 08;
 - Friday 14 Nov 08; and
 - Wednesday 26 Nov 08.
- 2.6 Observations made during the visits have been classified using a traffic light system. The following "classes of observation" have been used.

GENERAL: Routine site observation. No corrective action(s) needed;

 NOTABLE: Observation with potential environmental impacts; however risks associated with observations are not immediately significant and/or corrective actions can be (and have agreed to be) quickly implemented;

CRITICAL: Observation has immediate and/or major environmental risks.
 Urgent/immediate corrective action required, which may affect site operations or cannot be quickly implemented.

2.7 One inspection visit has been undertaken in conjunction with representatives of the Environment Agency to confirm respective responsibilities. Further joint inspections are likely when site activities change and the levels of environmental risk increase.

3 Observations and Corrective Actions

- During the reporting period, site activities carried out by Able UK under the MARAD contract have primarily focused on the stripping of asbestos from within ships. All stripped asbestos has been stored on-ship in accordance with the agreed method statements.
- 3.2 The following GENERAL observations have been made during the site visits.
 - The site is generally tidy.
 - Potentially contaminative materials, notably including oils, are stored in appropriate containment facilities.
 - Environmental monitoring results collected by Franks Portlock Consulting Limited show asbestos containment procedures employed during stripping activities are effective.
 - Asbestos training records, individual worker exposure monitoring, area inspection records and other asbestos strip documentation was found to be in order (HSE inspection of asbestos management procedures have also been carried-out with no apparent problems being identified).
- 3.3 The following **NOTABLE** observations have been made during site visits:
 - The oil containment boom around the MARAD ships was weighed-down with accumulated plant and animal biomass and this would have allowed oils, if released, to escape the contained area. (Note: this had also been identified by the Environment Agency).
 - A steel oil containment bund formally used for a temporary generator and associetd oil tank was noted to be half full of oily water. This represented a potential source of oil pollution if heavy rains result in the filling and overtopping of the bund.
- 3.4 Both of these issues have been addressed. The boom has been cleaned and accumulated biomass removed such that the boom now floats in an appropriate position to be effective in containing oil spillages. The bund has been drained of oily water and was being removed during the most recent site visit.
- 3.5 No **CRITICAL** observations have been made during the site visits undertaken during the reporting period.

4 Conclusions and Recommendations

Conclusions

- 4.1 No **CRITICAL** environmental issues have been identified during the current reporting period.
- 4.2 Two **NOTABLE** observations have been made and these have both been addressed by site management.
- 4.3 Overall, Scott Wilson is satisfied that during the inspections of the MARAD ships dismantling carried out to date that no activities were identified that either breach the agreed environmental protection measures or that were assessed to have a significant risk of causing significant environmental pollution or damage.

Recommendations

4.4 Environmental inspection visits should continue at a frequency commensurate with the levels of environmental risks associated with ongoing dismantling activities. The inspection visits should also continue on a random basis, and include a proportion of both announced and unannounced visits.

Appendix 1 Completed Site Inspection Proformas



	DAILY SITE ENV	IRONMEN	TAL	DIARY		*,
Project:	Dr		Date:	050908		
Project. IEI			Time:	1430	li .	
To: Gw	BIRT	Г	Cc:			
Location:	Comments:	Action:				
TERFC/	Ste necting + good					
MARAD	visit. Full she four					
	Ste meeting + general visit. Ful ste tour No ACTUSHIGES /155000 rego. rung action noted.					
	1,55000 1890, 1249					
3	action noted.					
		у.				
	×					
	- 4					
×	*					
	ě					: 1 ::
	· J					
19	to a second of the	7.				
	A. Carlotte and the car					
				s ()		
Inspector Signed:		Environmenta Signed:	al Manage	er 		
Print: AOUA	COOCIM CU	Print:				



	DAILY SITE ENV	RONMENTA	L DIARY
Project:	ERRC.	Dat	•
40 ***		Tim	
To: Cara	OPBRT.	Cc	:
	Comments:	Action:	
MARAD	Caspestos managens,		
	RIE, mondoring		
	and exposure files.		
	Co.	ALL IMAG	LAD to muestigate.
	Query raised re: Calibration Cent for	MBILLIAM	
	Calibration Con		
	DCD \$1. DCD NOT		
	DCO Ø1. DCO not in use at present.		
	,		
	,		
	*		
	,		
			arms of miterally
			Amolada.
Inspector		Environmental Man	ager PBardy
Signed:		Signed:	Paren
Print: ADK	COOLING CA	Print: PAV	L ISHIZCHA'



DAILY SITE ENVIRONMENTAL DIARY Project: TERRC Date: 01 10 08 Time: 1000 Location: Comments: Action: General site ok No site. Concerns identified below with level is thating groperly in a small number

Inspector
Signed:

Print: #00.40 MIND

Environmental Manager
Signed:

Print:



Site Environmental Inspector Observations

TERRC MARAD Environmental Inspections

Document No:

D115634\ Environmental inspections\Environmental Daily Site Diary

Title:

TERRC MARAD Ship Inspections.

Site Inspection Diary

Revision:

01

	Name (Position)	Comment	Date	Approved (Signature)
Scott Wilson	AORIAGO	SITE VISIT NO ACTIONS DENVILLED	171008	
MARAD Office				
ABLE House				
Hartlepool Borough Council				



DAILY SITE ENVIRONMENTAL DIARY

Project: TERRC

Date: 17 0ct 2008

Time: 10 40.

Location:	Comments:	Action:
SMIPS	ASBESTOS REMOJAL AND PREP WORKS BEING UNDERTAKEN. PREP WORRS.	NO ACTURS REQ.
Boch.	BOOM MANTENANCE BUNCE UNDERTAREN (AS REPORTED LAST VISIT).	

Inspector
Signed:

Print: Aonan nino

Environmental Manager Signed:

Print:



Site Environmental Inspector Observations

TERRC MARAD Environmental Inspections

Document No:

D115634\ Environmental inspections\Environmental Daily Site Diary

Title:

TERRC MARAD Ship Inspections.

Site Inspection Diary

Revision:

01

	Name (Position)	Comment	Date	Approved (Signature)
Scott Wilson	ASMAN MILTON	BOOM MANTENANCE COMPETED ASBESTOS BOUNDARY MONTERIAL RESULTS REVIEWS (ALL ON).	061108.	
MARAD Office				
ABLE House				
Hartlepool Borough Council				
			2	



DAILY SITE ENVIRONMENTAL DIARY				
Project: TER	Comments:		: 06 Nov 08. : 1300. Action:	
Doch.	BOOM MAINTENANCE LAGGIED 65T. VEZETATION SETC REMOSED & ADDITION BOOKS ADDED.	NAL.	MIC'	
SITE	OVARTERLY (FIFTH T. COMPASS POINT, A SOMEY CONFICTED SINCE MAST VISTE PRESIDENTS REVIEWED CHELIS MESO REVIEWED -	T (See a	NO ASBESTOS DETECTED DS ATT BOUNDAMY. ALL. NEZULTS LESS THAN 29/30 DOTOR). O.O.I REBOTABLE FIBRES (F/M) NIL	
SITE	No orner Comments.		NICI	

Inspec		
Print:	AONIX	Marin 1

Environmental Manager Signed:

Print: South Bond Manager Print: South



Site Environmental Inspector Observations

TERRC MARAD Environmental Inspections

Document No:

D115634\ Environmental inspections\Environmental

Daily Site Diary

Title:

TERRC MARAD Ship Inspections.

Site Inspection Diary

Revision:

01

	Name (Position)	Comment	Date	Approved (Signature)
Scott Wilson	ADRIAN MILTON (PRINCIPAL)	SUND WATER (CLOCKENNY BUND) NOTEDS REMOVER.	No. Oc.	
MARAD Office			V	
ABLE House				
Hartlepool Borough Council				
			ų.	



DAILY SITE ENVIRONMENTAL DIARY Date: 14 NOVEMBER 2008-Project: TERRC 1000 JUNANA Location: Comments: Action: SITE VISIT CAMINED OUT SITE. NIL wim REPS From ENVINONMENT ACENCY TO ENSURE COORDINATION ON INSPECTIONS SITE NO MAJOR GISSONATION FORMER STEEL GENNY REZULES EMPTINE. BUND 1/2 FULL WITH DILT WATER. BUND REPAIRS AROUND MARAD SHIPS NEAR Complete. SITE TIDY.

Inspec	tor			
Signed	:t			÷
3				
Print:	AON	LAC.	MIST	600



Site Environmental Inspector Observations

TERRC MARAD Environmental Inspections

Document No:

D115634\ Environmental inspections\Environmental

Daily Site Diary

Title:

TERRC MARAD Ship Inspections.

Site Inspection Diary

Revision:

01

	Name (Position)	Comment	Date	Approved (Signature)
Scott Wilson	ADRIAN MITTON (MISTOR)	NO SICH, FICAROT OBSEDRUTTON	26/1001/2	
MARAD Office				
ABLE House			-	e je
Hartlepool Borough Council				
			1,	2) ()



DAILY SITE ENVIRONMENTAL DIARY

Project: TERRC

Date: 26 NOVEMBER 2008

Location:	Comments:	Action:
SITE.	SITE CONSENALLY	
	DU COUNT BUND	
	mminent (vons	
	USIT)	
	No significant	NIC.
	OBSERVATIONS	

Inspect Signed	or :	
Print:	Donnes	MINON

Environmental Manager Signed: